

Boeing 767 Series Aeroplanes

---

**AD/B767/112**

**MLG Beam Outboard Support Fuse Pins**

**8/99**

- Applicability:** Model 767 series aircraft, line numbers 1 through 609; having 4330M steel fuse pins installed in the outboard support of the main landing gear (MLG) beam.
- Requirement:** Action in accordance with the technical requirements of FAA AD 99-11-14 Amdt 39-11185.
- Note: Installation of newer-type 15-5PH CRES fuse pins in accordance with Boeing Alert Service Bulletin 767-57A0054 Revision 2 or Revision 3 constitutes terminating action for the repetitive inspection requirements of this Directive.*
- Compliance:** As specified in the Requirement Document for the initial and repetitive inspection requirements, with a revised effective date of 12 August 1999.
- This Airworthiness Directive becomes effective on 12 August 1999.
- Background:** The FAA received a report of corrosion on a fuse pin in the outboard support of the MLG beam. Corrosion or chrome plating cracks could result in the failure of a fuse pin and consequent collapse of the landing gear.