
AIRWORTHINESS DIRECTIVE

For the reasons set out in the background section, the CASA delegate whose signature appears below issues the following Airworthiness Directive (AD) under subregulation 39.1 (1) of CASR 1998. The AD requires that the action set out in the requirement section (being action that the delegate considers necessary to correct the unsafe condition) be taken in relation to the aircraft or aeronautical product mentioned in the applicability section: (a) in the circumstances mentioned in the requirement section; and (b) in accordance with the instructions set out in the requirement section; and (c) at the time mentioned in the compliance section.

Cessna 180, 182 and Wren 460 Series Aeroplanes

AD/CESSNA 180/83

KAP 140 Autopilot System

2/2004

Applicability: Cessna 182S, 182T and T182T model aeroplanes listed below that are equipped with a Honeywell KAP 140 autopilot computer system, part number (P/N) 065-00176-2602, 065-00176-5402 or 065-00176-7702.

Model	Serial Numbers
182S	18280001 through 18280944
182T	18280945 through 18281064, 18281067 through 18281145, 18281147 through 18281163, 18281165 through 18281167 and 18281172
T182T	T18208001 through T18208109 and T18208111 through T18208177

- Requirement:**
1. Unless previously accomplished, install and update the KC 140 autopilot computer system operating software in accordance with Honeywell Service Bulletin KC 140-M1 dated August 2002, as specified in Cessna Service Bulletin SB02-22-01 dated 25 November 2002.
 2. Following Requirement 1 software installation, re-identify the KC-140 unit as follows:
 - a. Change the unit part number by attaching flavour sticker, P/N 057-02203-0003, on the unit's serial tag;
 - b. Attach an M decal, P/N 057-02984-0501, in front of the unit's serial number (this indicates that the unit's P/N has been changed); and
 - c. Attach a software mod tag, P/N 057-05287-0301, in place of the old tag to indicate the software change to SW MOD 03/01.
 3. KC 140 autopilot computer systems P/Ns 065-00176-2602, 065-00176-5402 and 065-00176-7702 may not be installed on any Cessna Model 182S, 182T or T182T aeroplanes as a replacement part unless the computer has been modified as specified in Requirements 1 and 2 of this Directive.

Note: FAA AD 2003-24-13 Amdt 39-13382 refers.

Cessna 180, 182 and Wren 460 Series Aeroplanes

AD/CESSNA 180/83 (continued)

Compliance: For Requirement 1 - Within 100 hours time in service after the effective date of this Directive.

For Requirement 2 - Before further flight after installing the update to the KC 140 autopilot computer system operating software.

For Requirement 3 - As of the effective date of this Directive.

This Airworthiness Directive becomes effective on 19 February 2004.

Background: The United States Federal Aviation Administration (FAA) has received reports of inadvertent and undetected engagement of the autopilot system in Cessna Models 172R, 172S, 182S, 182T, T182T, 206H, and T206H aeroplanes. These aeroplanes are equipped with a Honeywell KAP 140 autopilot computer system installed in the centre instrument control panel near the throttle.

This Directive requires the installation of an update to the operating software of the KAP 140 autopilot computer system, a change to the unit's part number and change of the software modification identification tag. These actions prevent unintentional engagement of the KAP 140 autopilot computer system, which could cause the pilot to take inappropriate actions.



David Villiers
Delegate of the Civil Aviation Safety Authority

7 January 2004