



## Airworthiness Directive

**AD No.:** 2022-0057

**Issued:** 28 March 2022

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

### Design Approval Holder's Name:

AIRBUS

### Type/Model designation(s):

A330 and A340 aeroplanes

**Effective Date:** 11 April 2022

**TCDS Number(s):** EASA.A.004 and EASA.A.015

**Foreign AD:** Not applicable

**Supersedure:** None

## ATA 56 – Windows – Windshields – Inspection

---

### Manufacturer(s):

Airbus, formerly Airbus Industrie

### Applicability:

A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, A330-343, A330-743L, A330-841, A330-941 aeroplanes, all manufacturer serial numbers (MSN); and

A340-211, A340-212, A340-213, A340-311, A340-312, A340-313, A340-541, A340-542, A340-642 and A340-643 aeroplanes, all MSN.

### Definitions:

For the purpose of this AD, the following definitions apply:

**Affected part:** SAINT-GOBAIN SULLY (SGS) front windshields having a Part Number (P/N) as defined in Table 1 of this AD. Depending on its P/N, an affected part is Group 1, Group 2 or Group 3, as defined in the SB.

**New/repaired part:** Any affected part which is new; or which has accumulated 0 flight hours (FH) since repaired by SGS, including "Outer ply replacement".



**Serviceable part:** Any windshield, eligible for installation, which is not an affected part; or an affected part which is a new/repaired part, as defined in this AD; or an affected part which is not a new/repaired part that, before next installation, or before next flight after installation, passes (no defects found) a detailed inspection (DET) and passes (results included in the “green area” or “amber area”, as identified in the SB) an electrical test measurement (ETM), as applicable, in accordance with the instructions of the SB.

**Aeroplane date of manufacture:** The date of transfer of title (ownership) which is referenced in Airbus documentation at the time of first delivery to an operator.

**Date of first installation:** For an affected part, the date of first installation on an aeroplane. If unknown, or for a part not replaced in service, the aeroplane date of manufacture must be used instead.

**The SB:** Airbus Service Bulletin (SB) A330-56-3010, or Airbus SB A340-56-4009, or Airbus SB A340-56-5003, as applicable, and SGS SB SPS A340-56-001.

**Groups:**

Group A aeroplanes are those that have an affected part installed.

Group B aeroplanes are those that do not have an affected part installed.

Note 1: An aeroplane on which Airbus modification 209046 has been embodied in production (only windshields installed having P/N SPSA340-1-6-3 and P/N SPSA340-2-6-3) is Group B, provided that no affected part has been installed on that aeroplane since its date of manufacture.

**Reason:**

An occurrence was reported where an A319 aeroplane lost the right-hand front windshield in flight, with consequent rapid cockpit depressurization, causing damage to cockpit items/systems and significant increase of flight crew workload. The investigations identified several contributing factors (including manufacturing variability, fretting between windshield components, water ingress, electrical braids corrosion) which led to a thermal shock/overheat, damaging more than one windshield structural plies and impairing the structural integrity of the windshield. Due to the design similarity, this condition can also exist or develop on A330 and A340 aeroplanes.

This condition, if not detected and corrected, could lead to failure of the windshield, possibly resulting in injury to the flight crew, in-flight depressurization of the aeroplane, and would require exceptional piloting skill to maintain control of the aeroplane.

To address this potential unsafe condition, Airbus issued the SB to provide inspection instructions for the affected parts.

For the reasons described above, this AD requires repetitive DET and ETM of the affected parts, and, depending on findings, accomplishment of applicable corrective action(s).



**Required Action(s) and Compliance Time(s):**

Required as indicated, unless accomplished previously:

Table 1 – Affected Parts P/N and Groups

Affected Part Group	SGS Windshield P/N	
	Left-hand side	Right-hand side
1	SPSA340-2-4-1	SPSA340-1-4-1
2	SPSA340-2-5-2	SPSA340-1-5-2
3	SPSA340-2-1-1	SPSA340-1-1-1
	SPSA340-2-2-1	SPSA340-1-2-1
	SPSA340-2-3-1	SPSA340-1-3-1

**Inspection(s):**

- (1) For Group A aeroplanes: Within the compliance time as specified in Table 2 of this AD, and thereafter, at intervals not exceeding 800 FH or 4 months, whichever occurs first, accomplish a DET followed by an ETM of each Group 1 affected part in accordance with the instructions of the SB.

Table 2 – Group 1 Affected Parts – Initial DET / ETM

Compliance Time (whichever occurs later, A or B)	
<b>A</b>	Within 800 FH or 4 months, whichever occurs first after the effective date of this AD
<b>B</b>	Before exceeding 800 FH or 4 months, whichever occurs first since the date of first installation

- (2) For Group A aeroplanes: Within the compliance time as specified in Table 3 of this AD, as applicable, and, thereafter, at intervals not exceeding 10 000 FH or 24 months, whichever occurs first, accomplish a DET followed by an ETM of each Group 2 affected part in accordance with the instructions of the SB.

Table 3 – Group 2 Affected Parts – Initial DET / ETM

Compliance Time (whichever occurs later, A or B)	
<b>A</b>	Within 800 FH or 4 months, whichever occurs first after the effective date of this AD
<b>B</b>	Before exceeding 800 FH or 4 months, whichever occurs first since the date of first installation

- (3) For Group A aeroplanes: The initial DET followed by ETM of each Group 2 affected part, as required by paragraph (2) of this AD can be postponed to the special compliance times specified in Table 4 of this AD, provided the conditions specified in Table 4 of this AD are met.



Table 4 – Group 2 Affected Parts – Initial DET / ETM

<b>Windshield Maintenance History &amp; Operational Test results as specified in the SB</b>	<b>Windshield Age / Utilization (see Note 2)</b>	<b>Special Compliance Time(s) for the DET and ETM (after the effective date of this AD, or since the date of first installation, whichever occurs later)</b>
Fault message 561111 L WSHLD SENSOR(3DG1)/ WHC1 (2DG1)" or "561111 R WSHLD SENSOR(3DG2)/ WHC2 (2DG2)" NOT recorded since windshield installation on an aeroplane  <b>AND</b>  Fault message 561111 L WSHLD SENSOR(3DG1)/ WHC1 (2DG1)" or "561111 R WSHLD SENSOR(3DG2)/ WHC2 (2DG2)" NOT found	More than 48 months, or more than 10 000 flight cycles (FC), or 15 000 FH	Within 5 000 FH or 12 months, whichever occurs first
	Less than, or equal to 48 months, <u>and</u> less than, or equal to 10 000 FC and 15 000 FH	Within 10 000 FH or 24 months, whichever occurs first

Note 2: Should a lack of data impair the determination of the windshield age/utilisation, operators may refer to the SB – section Accomplishment Instruction / C. Procedure / Note.

- (4) If, during any ETM as required by paragraph (2) or (3) of this AD, as applicable, the results are found to be in the “amber area”, as identified in the SB, accomplish subsequent DET and ETM of that affected part at intervals not exceeding 800 FH or 4 months, whichever occurs first.
- (5) For Group A aeroplanes: Within the compliance time as specified in Table 5 of this AD, as applicable, and, thereafter, at intervals not exceeding 800 FH or 4 months, whichever occurs first, accomplish a DET of each Group 3 affected part in accordance with the instructions of the SB.

Table 5 – Group 3 Affected Parts – Initial DET

<b>Compliance Time (whichever occurs later, A or B)</b>	
<b>A</b>	Within 800 FH or 4 months, whichever occurs first after the effective date of this AD
<b>B</b>	Before exceeding 800 FH or 4 months, whichever occurs first since the date of first installation

#### **Corrective Action(s):**

- (6) If, during any DET as required by paragraph (1), (2), (3) or (5) of this AD, as applicable, any defect, as identified in the SB, is found on an affected part, before next flight, replace that affected part with a serviceable part in accordance with the instructions of the SB.



- (7) If, during any ETM as required by paragraph (1), (2) or (3) of this AD, as applicable, the results are found to be in the “red area”, as identified in the SB, before next flight, replace that affected part with a serviceable part in accordance with the instructions of the SB.
- (8) Replacement of an affected part with a serviceable part on an aeroplane, as required by paragraph (6) or (7) of this AD, as applicable, can be deferred in accordance with the applicable instructions and limitations of Master Minimum Equipment List (MMEL) item 30-42-03A.

**Terminating Action:**

- (9) For Group A aeroplanes: Replacement on an aeroplane of each affected part with a windshield having a P/N not affected by the requirements of this AD constitutes terminating action for the repetitive inspections as required by paragraphs (1), (2), (3), (4) and (5) of this AD, as applicable for that aeroplane, provided that, following that replacement, no affected part is installed on that aeroplane.

**Parts Installation:**

- (10) For Group A and Group B aeroplanes: From the effective date of this AD, it is allowed to install on any aeroplane a windshield, provided it is a serviceable part, as defined in this AD. Following installation of an affected part on an aeroplane, that aeroplane is effectively a Group A aeroplane, and that affected part must be inspected as required by this AD. For an affected part which is not a new/repairs part, as defined in this AD, the first inspection after that installation can be deferred up to the applicable interval for repetitive inspection, provided that part has accumulated 0 FH since the last inspection and has been stored in accordance with the instructions of the applicable Component Maintenance Manual.

**Reporting:**

- (11) Within 30 days after accomplishment of the initial DET/ETM as required by paragraph (1), (2), (3) or (5) of this AD, as applicable, or within 30 days after the effective date of this AD, whichever occurs later, report the inspection results (including no findings) to Airbus. Using the inspection report attached to the SB is an acceptable method to comply with this requirement.
- (12) Within 90 days after each subsequent DET/ETM as required by paragraph (1), (2), (4) or (5) of this AD, as applicable, report any inspection finding to Airbus. Using the inspection report attached to the SB is an acceptable method to comply with this requirement.

**Ref. Publications:**

Airbus SB A330-56-3010 original issue dated 19 November 2021.

Airbus SB A340-56-4009 original issue dated 19 November 2021.

Airbus SB A340-56-5003 original issue dated 19 November 2021.

SGS SB SPS A340-56-001 original issue dated 25 October 2021.



The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 20 December 2021 as PAD 21-182 for consultation until 17 January 2022. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS – IIAL (Airworthiness Office), E-mail: [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com).

