

[Federal Register Volume 81, Number 86 (Wednesday, May 4, 2016)]
[Rules and Regulations]
[Pages 26682-26685]
From the Federal Register Online via the Government Publishing Office [www.gpo.gov]
[FR Doc No: 2016-10158]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-6147; Directorate Identifier 2016-NM-021-AD; Amendment 39-18506; AD 2016-09-08]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-8 series airplanes. This AD requires a detailed inspection for correct installation of the flex hose clamp of the occupant backup air supply and a general visual inspection for damage of the flex hose, and related investigative and corrective actions if necessary. This AD was prompted by a report indicating that flex hoses of the occupant backup air supply were found disconnected from the adjacent fiberglass duct on two airplanes. We are issuing this AD to detect and correct an incorrect clamp installation on the inboard end of the flex hose, which allows the flex hose to slowly become disconnected from the adjacent fiberglass duct, and damage to the hose. This condition, in conjunction with a cargo fire event, can potentially lead to decreased airflow to the main deck, possibly resulting in smoke and/or toxic fumes penetrating into the main deck passenger compartment, which could result in injury to the passengers or cabin crew.

DATES: This AD is effective May 19, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 19, 2016.

We must receive comments on this AD by June 20, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: 202-493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6147.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6147; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Stanley Chen, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6585; fax: 425-917-6590; email: stanley.chen@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We have received a report indicating that an operator, while on a maintenance visit, found a flex hose of the occupant backup air supply disconnected from the adjacent fiberglass duct on two airplanes. One of the flex hoses had a tear on the disconnected edge. A Boeing investigation found that these incidents were caused by the incorrect clamp installation on the inboard end of the flex hose, which is a quality control problem that allowed the flex hose to slowly become disconnected from the adjacent fiberglass duct. No related system faults were reported. We are issuing this AD to detect and correct an incorrect clamp installation on the inboard end of the flex hose, which allows the flex hose to slowly become disconnected from the adjacent fiberglass duct, and damage to the hose. This condition, in conjunction with a cargo fire event, can potentially lead to decreased airflow to the main deck, possibly resulting in smoke and/or toxic fumes penetrating into the main deck passenger compartment, which could result in injury to the passengers or cabin crew.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Service Bulletin 747-21A2571, dated December 4, 2015. The service information describes procedures for a detailed visual inspection of the clamp installation on the inboard end of the flex hose and general visual inspection of the flex hose for damage, and related investigative and corrective actions if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires accomplishing the actions specified in the service information described previously.

The phrase "related investigative actions" is used in this AD. Related investigative actions are follow-on actions that (1) are related to the primary action, and (2) further investigate the nature of any condition found. Related investigative actions in an AD could include, for example, inspections.

The phrase "corrective actions" is used in this AD. Corrective actions correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

FAA's Justification and Determination of the Effective Date

There are currently no domestic operators of this product. Therefore, we find that notice and opportunity for prior public comment are unnecessary and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the ADDRESSES section. Include the docket number FAA-2016-6147 and Directorate Identifier 2016-NM-021-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

Currently, there are no affected airplanes on the U.S. Register. However, if an affected airplane is imported and placed on the U.S. Register in the future, we estimate the following costs to comply with this AD:

Estimated Costs		
Action	Labor cost	Cost per product
Inspection of inboard end of the flex hose	3 work-hours × \$85 per hour = \$255 per inspection cycle	\$255 per inspection cycle

We estimate the following costs to do any necessary repairs that would be required based on the results of the inspection. We have no way of determining the number of aircraft that might need this repair:

On-Condition Costs

Action	Labor cost	Parts cost	Cost per product
Repair or replacement of inboard end of the flex hose	Up to 3 work-hours × \$85 per hour = \$255	\$65 per flex hose	\$320

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):



2016-09-08 The Boeing Company: Amendment 39-18506; Docket No. FAA-2016-6147; Directorate Identifier 2016-NM-021-AD.

(a) Effective Date

This AD is effective May 19, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 747-8 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-21A2571, dated December 4, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 21, Air conditioning.

(e) Unsafe Condition

This AD was prompted by a report indicating that flex hoses of the occupant backup air supply were found disconnected from the adjacent fiberglass duct on two airplanes. We are issuing this AD to detect and correct an incorrect clamp installation on the inboard end of the flex hose, which allows the flex hose to slowly become disconnected from the adjacent fiberglass duct, and damage to the hose. This condition, in conjunction with a cargo fire event, can potentially lead to decreased airflow to the main deck, possibly resulting in smoke and/or toxic fumes penetrating into the main deck passenger compartment, which could result in injury to the passengers or cabin crew.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Repair of Backup Air Supply Clamp and Flex Hose

Except as required by paragraph (h) of this AD, at the applicable time in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-21A2571, dated December 4, 2015, do a detailed inspection for correct installation of the backup air supply clamp, and before further flight, do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-21A2571, dated December 4, 2015.

(h) Exception to the Service Information

Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-21A2571, dated December 4, 2015, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Stanley Chen, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6585; fax: 425-917-6590; email: stanley.chen@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 747-21A2571, dated December 4, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 21, 2016.

John P. Piccola, Jr.,
Acting Manager, Transport Airplane Directorate,
Aircraft Certification Service.