



# Airworthiness Directive

**AD No.:** 2025-0240

**Issued:** 27 October 2025

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

**Design Approval Holder's Name:**

FOKKER SERVICES B.V.

**Type/Model designation(s):**

F27 aeroplanes

**Effective Date:** 10 November 2025

**TCDS Number(s):** EASA.A.036

**Foreign AD:** Not applicable

**Supersedure:** This AD supersedes EASA AD 2025-0085 dated 14 April 2025.

## ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitations Section Part 2, Airworthiness Limitation Items and Safe Life Items – Amendment

**Manufacturer(s):**

Fokker Aircraft B.V.

**Applicability:**

Fokker F27 Mark 050, F27 Mark 0502 and F27 Mark 0604 aeroplanes, all serial numbers.

**Definitions:**

For the purpose of this AD, the following definitions apply:

**The ALS:** Fokker Services (FS) "Airworthiness Limitations Section Part 2, Fokker 50/60 Airworthiness Limitation Items (ALI's) and Safe Life Items (SLI's)", Report SE-622, Issue 17.

**The AMP:** The Aircraft Maintenance Programme (AMP) contains the tasks on the basis of which the scheduled maintenance is conducted to ensure the continuing airworthiness of each operated aircraft. For aircraft operated under EU regulations, the operator or the owner ensures compliance with the AMP as stipulated in Commission Regulation (EU) [1321/2014](#).

**New and/or more restrictive tasks and limitations:** This includes all tasks and limitations that are new and all tasks for which a threshold or interval was reduced, as applicable, which were



introduced into the ALS, as defined in this AD, since the previous ALS revision that is currently incorporated in the AMP.

#### Reason:

The airworthiness limitations and certification maintenance instructions for the Fokker F27 Mark 050, Mark 0502 and Mark 0604 aeroplanes, which are approved by EASA, are currently defined and published in the FS F50 Airworthiness Limitations Section (ALS) documents.

FS ALS Part 2, Report SE-622, contains the Structural ALIs and the Retirement Lives for SLIs. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

EASA previously issued AD 2025-0085, requiring the actions described in ALS Part 2, Report SE-622, at Issue 16.

Since that AD was issued, FS published the ALS, as defined in this AD, containing new and/or more restrictive maintenance tasks and limitations.

For the reason described above, this AD retains the requirements of EASA AD 2025-0085, which is superseded, and requires accomplishment of the actions and limitations specified in the ALS.

#### Required Action(s) and Compliance Time(s):

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

#### Maintenance Tasks and Replacement of Life Limited Parts:

- (1) From the effective date of this AD, accomplish the following actions, as specified in the ALS, as applicable to aeroplane model and depending on aeroplane configuration (see Note 1 of this AD):
  - (1.1) Replace each component before exceeding the applicable (retirement) life limit, and
  - (1.2) Within the thresholds and intervals, accomplish all applicable maintenance tasks.

Note 1: For the purpose of this AD, the thresholds and intervals as defined in the 'Compliance Time' pages of the ALS include specific compliance times for certain tasks.

#### Corrective Action(s):

- (2) In case of finding discrepancies (as defined in the ALS) during accomplishment of any task as required by paragraph (1) of this AD, within the compliance time specified in the ALS, accomplish the applicable corrective action(s) in accordance with the applicable FS maintenance documentation. If no compliance time is identified in the ALS, accomplish the applicable corrective action(s) before next flight. If a detected discrepancy is not identified in the ALS, before next flight, contact FS for approved instructions and accomplish those instructions accordingly.



**AMP Revision:**

- (3) Within 12 months after the effective date of this AD, revise the approved AMP by incorporating the limitations, tasks and associated thresholds and intervals described in the ALS, as applicable to aircraft model and depending on aircraft configuration.

**Credit:**

- (4) If, before the effective date of this AD, the AMP has been revised to incorporate the maintenance tasks and life limitations as specified in a previous ALS revision, that action ensures the continued accomplishment of those tasks and limitations.

Consequently, for an aircraft to which that AMP applies, it is acceptable to accomplish the new and/or more restrictive tasks and limitations as specified in the ALS, as applicable to aircraft model and depending on aircraft configuration, within the compliance times as specified in the ALS, to comply with paragraph (1) of this AD.

For that AMP, it is acceptable to incorporate the new and/or more restrictive tasks and limitations as specified in the ALS, as applicable to aircraft model and depending on aircraft configuration, into the AMP to comply with paragraph (3) of this AD.

**Recording AD Compliance:**

- (5) When the AMP of an aircraft has been revised as required by paragraph (3) or (4) of this AD, as applicable, that action ensures continued accomplishment of the tasks and limitations as required by paragraphs (1) and (2) of this AD for that aircraft. Consequently, after revising the AMP, as required by paragraph (3) or (4) of this AD, as applicable, it is not necessary that accomplishment of individual action is recorded for demonstration of AD compliance on a continued basis.

**Ref. Publications:**

FS "Airworthiness Limitations Section Part 2, Fokker 50/60 Airworthiness Limitation Items (ALI's) and Safe Life Items (SLI's)", Report SE-622, Issue 17 dated 01 August 2025.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

**Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. This AD was posted on 26 September 2025 as PAD 25-152 for consultation until 24 October 2025. No comments were received during the consultation period.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety](#)



[reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.

5. For any question concerning the technical content of the requirements in this AD, please contact: Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL, Hoofddorp, The Netherlands, Telephone +31-88-6280-350, Fax +31-88-6280-111, E-mail: [technicalservices@fokkerservices.com](mailto:technicalservices@fokkerservices.com).  
The referenced publication can be downloaded from [www.myfokkerfleet.com](http://www.myfokkerfleet.com).

