Lycoming Piston Engines

AD/LYC/76 Amdt 6

Propeller Attachment Flange

10/94

Applicability:

All Lycoming O-360, IO-360, AIO-360 and AEIO-360 engines fitted with a light flange crankshaft and installed in an aircraft with a Certificate of Airworthiness in the acrobatic category or a Airplane Flight Manual approving aerobatic manoeuvres.

Note 1: For the purpose of this Directive, a light flange crankshaft is a crankshaft incorporating lightening holes in a 0.38" thick propeller attachment flange.

Requirement:

- 1. Carry out a visual inspection of the propeller attachment flange in accordance with Lycoming Service Bulletin No. 465C, "INSPECTION PROCEDURE I", or
- Carry out a Magnetic Particle Inspection (MPI) of the propeller attachment flange in accordance with Lycoming Service Bulletin No. 465C, "INSPECTION PROCEDURE II", or
- 3. Carry out an Eddy Current Inspection (ECI) of the propeller attachment flange in accordance with a procedure approved by the Authority.

Note 1: FAA Airworthiness Directive 84-13-05 refers.

Note 2: Replacement of a light flange crankshaft with a solid flange crankshaft is the terminating action for this Directive. A solid flange crankshaft does not have lightening holes in the propeller flange and the flange can be 0.38" or 0.44" thick.

Compliance:

Effective 15 September 1994:

- 1. Within 25 hours time in service, and thereafter at intervals not to exceed 25 hours time in service.
- 2. Unless previously accomplished, within 25 hours time in service, and thereafter at intervals not to exceed 110 hours time in service.
- 3. Unless previously accomplished, within 25 hours time in service, and thereafter at intervals not to exceed 110 hours time in service.

Background:

This Directive has been amended, in part, to reflect the manufacturer's latest revision to the requirement document. Service Bulletin No. 465C provides a terminating action for engines fitted with light flange crankshafts.

The amendment also deletes direct reference to an Eddy Current Inspection (ECI) procedure detailed in a previous issue of this Directive. Inspection of the propeller flange by ECI shall be carried out in accordance with a procedure approved by the Authority.