EASA

AIRWORTHINESS DIRECTIVE

AD No.: 2013-0009

Date: 11 January 2013

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with EC 748/2012, Part 21.A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [EC 2042/2003 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].

AGUSTAWESTL	· · · · · · · · · · · · · · · · · · ·	Type/Model designation(s) : A109 and A119 helicopters			
TCDS Number:	EASA.R.005				
Foreign AD:	Not applicable				
Supersedure: None					
ATA 64	Tail Rotor – Blade Retaining Bolts – Inspection / Replacement				
Manufacturer(s):	AgustaWestland S.p.A (formerly Agusta S.p.A.), AgustaWestland Philadelphia Corporation (formerly Agusta Aerospace Corporation).				
Applicability:	A109C, A109K2, A109E and A119 helicopters, all serial numbers (s/n).				
Reason:	Cases of cracked tail rotor (TR) blade retaining bolts, part number (P/N) 109-8131-09-1 installed on an A109K2 and on an A109E helicopter, have been reported. The investigation of these occurrences carried out by AgustaWestland revealed that the cracks were in the same area of the bolts and in correspondence with some corrosion pits.				
	This condition, if not detected and corrected, could cause damage to, or loss of, a TR blade, possibly resulting in loss of control of the helicopter.				
	above, this AD requires a one-time visual and liquid ade retaining bolts. Thereafter, this AD also requires a TR blade retaining bolts and, if any crack, corrosion aplishment of the applicable corrective actions.				
Effective Date:	25 January 2013				

Required Action(s)	Required	l as indicated, unless a	ccomplish	ed previously:	
and Compliance Time(s):	(1) Within the compliance time as specified in Table 1 of this AD, depending on the time in service of the TR blade retaining bolts on the effective date of this AD, accomplish a visual and liquid penetrant inspection of the retaining bolts P/N 109-8131-09-1 in accordance with the instructions of Part I of AgustaWestland Bollettino Tecnico (BT) 109-135, BT 109K-55, BT 109EP- 125 or BT 119-052, as applicable, depending on helicopter model.				
		Та	able 1 – First inspection		
	the	Flight Hours (FH) accumulated by the TR blade retaining bolts on the effective date of this AD		Compliance time	
	Les	Less than 400 FH		Before exceeding 500 FH accumulated by the retaining bolts	
	400) FH or more		Within 100 FH or 2 months, whichever occurs first after the effective date of this AD	
	(2) After accomplishment of the inspection as required by paragraph (1) of this AD, within the compliance time specified in Table 2 of this AD, accomplish repetitive inspections of the TR blade retaining bolts P/N 109-8131-09-1 in accordance with the instructions of Part II of AgustaWestland BT 109-135, BT 109K-55, BT 109EP-125 or BT 119-052, as applicable, depending on helicopter model.				
	Table 2				
		Helicopter Model(s)	Complia	nce time - Interval	
		A109C		300 FH helicopter inspection" or at not to exceed 6 months, whichever irst	
		A109K2, A109E and A119		"200 FH helicopter inspection" or at not to exceed 6 months, whichever rst	
	(3) If, during any inspection as required by paragraph (1) or (2) of this AD, any crack, corrosion, damage or removal of cadmium plating in the central part of the bolt is identified, before next flight, replace the affected TR blade retaining bolt P/N 109-8131-09-1 with a serviceable part in accordance with the instructions of AgustaWestland BT 109-135, BT 109K-55, BT 109EP-125 or BT 119-052, as applicable, depending on helicopter model.				
	 (4) Replacement of TR blade retaining bolts as required by paragraph (3) of this AD does not constitute terminating action for the inspections as required by paragraphs (1) and (2) of this AD. 				
	(5) From the effective date of this AD, do not install a TR retaining bolt P/N 109-8131-09-1 that has accumulated more than 400 FH, on any helicopter unless it has passed the inspections as required by paragraph (1) of this AD.				
Ref. Publications:	AgustaWestland BT 109-135 dated 19 December 2012.				
	AgustaWestland BT 109K-55 dated 19 December 2012.				
	AgustaWestland BT 109EP-125 dated 19 December 2012.				
	AgustaWestland BT 119-052 dated 19 December 2012.				
		of later approved revis ice with the requiremer		ese documents is acceptable for AD.	

Remarks:	1.	If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
	2.	Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication.
	3.	Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: <u>ADs@easa.europa.eu</u> .
	4.	For any question concerning the technical content of the requirements in this AD, please contact: Agusta S.p.A. Customer Support Via del Gregge, 100 - 21015 Lonate Pozzolo (VA) – Italy Telephone + 39 0331 664600 ; Fax: + 39 0331 664684 E-mail: <u>custserv@agustawestland.com</u> .