	EASA	AIRWORTHINESS DIRECTIVE		
	X	AD No.: 2012-0033R1		
		Date: 27 February 2012		
		Note: This Airworthin Regulation (EC) No 2 and of the European 66 of that Regulation.	ess Directive (AD) is issued by EASA, acting in accordance with 16/2008 on behalf of the European Community, its Member States third countries that participate in the activities of EASA under Article	
	This AD is issued in accordance of continuing airworthiness of an airco an aircraft to which an AD applies, [EC 2042/2003 Annex I, Part M.A.C	with EC 1702/2003, Part 21A.3B. In accordance with EC 2042/2003 Annex I, Part M.A.301, the raft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate , except in accordance with the requirements of that AD unless otherwise specified by the Agency 303] or agreed with the Authority of the State of Registry [EC 216/2008, Article 14(4) exemption].		
	Type Approval Holder's Name :		Type/Model designation(s) :	
	EUROCOPTER		AS 350 B2 helicopters	
	TCDS Number : EASA.R.008			
	Foreign AD : Not applicable			
	Revision:	This AD revises EASA AD 2012-0033 dated 24 February 2012.		
	ATA 26	Fire Protection – Fire Detection System – Modification		
	Manufacturer(s):	Eurocopter, Euroco	pter France, Aerospatiale	
	Applicability:	AS 350 B2 helicopters, all serial numbers, if equipped with a Turbomeca ARRIEL 1D1 engine and incorporating Eurocopter modification (mod) 073273, except helicopters that incorporate mod 074346.		
	Reason:	Reports have been received, concerning three events with AS 350 B2 helicopters, in which the "FIRE ALARM" warning did not light up on the Cockpit Warning Panel (CWP) during a functional test of the power plan fire detection circuit.		
		The results of the investigation showed that these occurrences had caused by the fact that a resistor was missing, which had been interthrough mod 072598, but removed through mod 073273 even the 072598 was still logged in the helicopter documents.		
		This condition, if not detected and corrected, could lead to where an engine fire remains undetected, possibly resultine helicopter.		
		For the reasons des detection system (m modules (38W and	scribed above, this AD requires modification of the fire nod 074346) by installation of two additional resistor 39W).	
		This AD has been revised to amend the Applicability to match the definition in Eurocopter AS350 Alert Service Bulletin 26.00.02.		
	Effective Date:	27 February 2012		

Required Action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously: Within 40 flight hours or 75 calendar days, whichever occurs first after the effective date of this AD, modify the fire detection system by installing resistor modules 39W and 38W, in accordance with the instructions of paragraph 3 of Eurocopter AS350 Emergency Alert Service Bulletin (ASB) 26.00.02.	
Ref. Publications:	Eurocopter AS350 ASB 26.00.02 dated 23 February 2012. The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.	
Remarks :	 If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD. 	
	2. The required actions and the risk allowance have granted the issuance of a Final AD with Request for Comments, postponing the public consultation process after publication.	
	 Enquiries regarding this AD should be referred to the Safety Information Section, Executive Directorate, EASA. E-mail: <u>ADs@easa.europa.eu</u>. 	
	 For any question concerning the technical content of the requirements in this AD, please contact: EUROCOPTER - Customer Service Technical Support Department, Aéroport de Marseille, Provence 13725 Marignane Cedex – France Telephone: + 33 (0)4 42 85 99 51, Fax: + 33 (0)4 42 85 99 66. E-mail: <u>Directive.technical-support@eurocopter.com</u>. 	