



## Airworthiness Directive Cancellation Notice

**AD No.:** 2013-0133-CN

**Issued:** 16 February 2016

Note: This Airworthiness Directive (AD) Cancellation Notice (CN) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

**Design Approval Holder's Name:**

AIRBUS HELICOPTERS

**Type/Model designation(s):**

AS 350 and AS 355 helicopters

**Effective Date:** 16 February 2016

**TCDS Number(s):** EASA.R.008 and EASA.R.146

**Foreign AD:** Not applicable

**Cancellation:** This Notice cancels EASA AD 2013-0133 dated 28 June 2013.

### ATA 64 – CANCELLED: Tail Rotor – Tail Rotor Hub Pitch Horn – Inspection / Replacement

---

**Manufacturer(s):**

Airbus Helicopters, formerly Eurocopter, Eurocopter France, Aerospatiale

**Applicability:**

AS 350 B, AS 350 BA, AS 350 BB, AS 350 B1, AS 350 B2, AS 350 B3, AS 350 D, AS 355 E, AS 355 F, AS 355 F1, AS 355 F2, AS 355 N and AS 355 NP helicopters, all serial numbers, equipped with Tail Rotor Hub (TRH) pitch horn assemblies (hereafter called 'assembly') Part Number (P/N) 350A121368.01, P/N 350A121368.02, P/N 350A121368.03, or P/N 350A121368.04, incorporating TRH pitch horn (hereafter called 'part') P/N 350A121368.XX (where XX stands for two digit dash number excluding 01, 02, 03, and 04 which are reserved for assemblies).

Note: Either the assembly P/N or the part P/N can be marked on the affected TRH pitch horns.

**Reason:**

In 2013, an occurrence was reported of crack detection on the yoke of a TRH pitch horn.

This condition, if not detected and corrected, could lead to the failure of the two horn yokes and consequent loss of the anti-torque function, possibly resulting in loss of control of the helicopter.

To address that potential unsafe condition, Eurocopter issued AS350 Emergency Alert Service Bulletin (ASB) No. 05.00.74 and AS355 ASB No. 05.00.65, and, as an interim measure pending the outcome of investigations, EASA issued AD 2013-0133 to require repetitive visual inspections of the



affected TRH pitch horns to detect cracks and, depending on findings, replacement with a serviceable assembly.

Since that AD was issued, it was demonstrated that the cracks, as found in the reported event, can only occur when the additional chin weights, identified by modification (MOD) 07 5601, are installed. As this MOD was only applied on certain AS 350 B3 helicopters, and EASA AD 2013-0029 already addresses that unsafe condition, the repetitive inspections of the other helicopters, as required by EASA AD 2013-0133, are now considered redundant.

For the reasons described above, this Notice cancels EASA AD 2013-0133.

**Required Action(s) and Compliance Time(s):**

None.

**Ref. Publications:**

Airbus Helicopters AS350 Emergency ASB No. 05.00.74 Revision 2 dated 17 December 2015.

Airbus Helicopters AS355 Emergency ASB No. 05.00.65 Revision 2 dated 17 December 2015.

**Remarks:**

1. This AD-CN was posted on 15 January 2016 as PAD 16-002-CN for consultation until 12 February 2016. No comments were received during the consultation period.
2. Enquiries regarding this AD-CN should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
3. For any question concerning the technical content of this AD-CN, please contact:  
Airbus Helicopters – Aéroport de Marseille Provence, 13725 Marignane Cedex, France.  
Telephone +33 (4) 42 85 97 97, Fax +33 (4) 42 85 99 66;  
E-mail: [contact.msm.ah@airbus.com](mailto:contact.msm.ah@airbus.com).

