McDonnell Douglas (Hughes) and Kawasaki 369 Series Helicopters

| AD/HU 369/8 | 34 Tail Rotor Blades | 1/92 DM |
|----------------|--|-------------------------------|
| Applicability: | Model 369 Series fitted with the following tail rotor blades: | |
| | P/N 369D21613 | |
| | S/Ns 0646, 1165,1821. | |
| | P/N 369D21613M | |
| | S/Ns 1357, 1809, 1855. | |
| | P/N 369D21613-11 | |
| | S/Ns 2465, 2466, 2683. | |
| | P/N 369D21613-51 | |
| | S/Ns 4025, 4026, 4453, 4514, 4515, 4683, 02222-6097. | |
| | P/N 369D21613-501 | |
| | S/N 5308. | |
| Requirement: | Remove from service any tail rotor blade identified by the above serial numb listing. | er |
| | Note 1: Removed blades need to be returned to Rotor Blades (NZ) Ltd for re | work. |
| | Note 2: Air Transport NZ AD DCA/HU 369/59 refers. | |
| Compliance: | Unless already accomplished; prior to further flight after 20 November 1991 | |
| Background: | This Directive is issued in response to a NZ AD which was issued as the resurecent accident in New Zealand where a tail rotor blade abrasion strip separa flight. Initial investigation has indicated a defect with the tail rotor blade abrastrip attachment. The abrasion strips may appear free of bond separation or withis does not assure their airworthiness. The above identified tail rotor blade the same batch as the accident blade. | ted in asion voids, but |