



# Airworthiness Directive

**AD No.:** 2025-0278

**Issued:** 10 December 2025

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I Part M.A.301, or Annex Vb Part ML.A.301, as applicable, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I Part M.A.303, or Annex Vb Part ML.A.303, as applicable] or agreed with the Authority of the State of Registry [Regulation (EU) 2018/1139, Article 71 exemption].

**Design Approval Holder's Name:**

AIRBUS HELICOPTERS

**Type/Model designation(s):**

AS 332 helicopters

**Effective Date:** 24 December 2025

**TCDS Number(s):** EASA.R.002

**Foreign AD:** Not applicable

**Supersedure:** This AD supersedes EASA AD 2025-0146-E dated 10 July 2025.

## ATA 25 – Equipment / Furnishings – Emergency Sea Anchor Pin – Inspection / Replacement

### Manufacturer(s):

Airbus Helicopters (AH), formerly Eurocopter, Eurocopter France, Aérospatiale

### Applicability:

AS 332 L, AS 332 L1, AS 332 L2 and EC 225 LP helicopters, all serial numbers.

### Definitions:

For the purpose of this AD, the following definitions apply:

**The EASB:** AH Emergency Alert Service Bulletin (EASB) AS332-25-66-0002 Issue 002 or EASB EC225-25-66-0001 Issue 002, as applicable.

**Affected part:** Emergency sea anchor having Part Number (P/N) 704A42695001 (manufacturer P/N 204527-0) or P/N 704A42695002 (manufacturer P/N 204527-1), as applicable.

**Serviceable part:** An affected part that is new (never previously installed on a helicopter), or an affected part that passed an inspection (no defects found) in accordance with the instructions of the EASB.



**Groups:** Group 1 helicopters are those that have an affected part installed. Group 2 helicopters are those that do not have an affected part installed.

**Reason:**

An occurrence of a corroded emergency sea anchor pin was reported on a helicopter.

This condition, if not detected and corrected, could lead to breaking and detaching the anchor in flight, possibly resulting in damage to the rotors and loss of control of the helicopter.

To address this potential unsafe condition, AH issued the EASB AS332-25-66-0002 and EASB EC225-25-66-0001, both at original issue, providing instructions to inspect and, depending on findings, to replace the affected part. Consequently, EASA published AD 2025-0146-E, requiring an inspection of the affected part, and, depending on findings, its replacement.

Since that AD was issued, it has been determined that an additional inspection of the affected part must be accomplished, and AH issued the EASB, as defined in this AD, providing the corresponding inspection instructions.

For the reason described above, this AD retains the requirements of EASA AD 2025-0146-E, which is superseded, and requires an additional inspection of the affected part.

This AD is still considered to be an interim action and further AD action may follow.

**Required Action(s) and Compliance Time(s):**

Required as indicated by this AD, unless the action(s) required by this AD have been already accomplished:

**Inspection:**

- (1) For Group 1 helicopters which have not been inspected in accordance with the instructions of AH EASB AS332-25-66-0002 or EASB EC225-25-66-0001, at original issue: Within 10 flight hours (FH) or 7 days, whichever occurs first after 14 July 2025 [the effective date of EASA AD 2025-0146-E], inspect the affected part in accordance with the instructions of the EASB.
- (2) For Group 1 helicopters which have been inspected in accordance with the instructions of AH EASB AS332-25-66-0002 or EASB EC225-25-66-0001, at original issue: Within 55 FH or 30 days, whichever occurs first after the effective date of this AD, inspect the affected part in accordance with the instructions of the EASB.

**Replacement:**

- (3) If, during the inspection as required by paragraph (1) or (2) of this AD, as applicable, any discrepancy, as defined in the EASB is detected, within the compliance time as specified in Table 1 of this AD, replace the affected part with a serviceable part in accordance with the instructions of the EASB.



Table 1 – Replacement Compliance Time

<b>Measurement Indication</b>	<b>Compliance Time</b> (after the inspection as required by paragraph (1) or (2) of this AD, as applicable)
Diameter of the pin in the most damaged location is equal or less than 8.00 mm	Before next flight
Diameter of the pin in the most damaged location is more than 8.00 mm and equal or less than 10.00 mm	Within 150 FH or 3 months, whichever occurs first
Diameter of the pin in the most damaged location is more than 10.00 mm and equal or less than 11.00 mm	Within 300 FH or 8 months, whichever occurs first

- (4) As an alternative to the replacement of the affected part, as required by paragraph (3) of this AD, it is allowed to install a locally made plug in accordance with the instructions of the EASB, provided that the plug is manufactured in accordance with instructions provided by AH and, thereafter, it is replaced with a serviceable part within 6 months after the installation of the locally made plug.

#### **Part(s) Installation:**

- (5) For Group 1 and Group 2 helicopters: From the effective date of this AD, it is allowed to (re)install an affected part on a helicopter, provided that it is a serviceable part, as defined in this AD.

#### **Ref. Publications:**

AH EASB AS332-25-66-0002 original issue dated 02 July 2025, and Issue 002 dated 02 December 2025.

AH EASB EC225-25-66-0001 original issue dated 02 July 2025, and Issue 002 dated 02 December 2025.

The use of later approved revisions of the above-mentioned documents is acceptable for compliance with the requirements of this AD.

#### **Remarks:**

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. Based on the required actions and the compliance time, EASA have decided to issue a Final AD with Request for Comments, postponing the public consultation process until after publication. All interested persons may send their comments, referencing the AD Number, to the E-mail address specified in below Remark 3, prior to 07 January 2026. Only if any comment is received



during the consultation period, a Comment Response Document will be published in the [EASA Safety Publications Tool](#), in a compressed ('zipped') file, attached to the record for this AD.

3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu).
4. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this AD, and which may occur, or have occurred on a product, part or appliance not affected by this AD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this AD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
5. For any question concerning the technical content of the requirements in this AD, please contact: : Airbus Helicopters (Technical Support), Aéroport de Marseille Provence 13725 Marignane Cedex, France, Telephone +33 (0)4 42 85 97 97, Fax +33 (0)4 42 85 99 66, Web portal: <https://keycopter.airbushelicopters.com> > Technical Requests Management, E-mail: [TechnicalSupport.Helicopters@airbus.com](mailto:TechnicalSupport.Helicopters@airbus.com).

