## COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Allison Turbine Engines - 250 Series

## AD/AL 250/79 Fuel Control Bellows Replacement 4/99

Applicability: All Allison Model 250-C18, C20, C28, C30, C20R, B15, B17, B17F series engines

fitted with a main fuel control incorporating a beryllium copper Pc bellows.

Requirement: Replace the beryllium copper bellows assembly with an inconel 718 stainless steel

bellows assembly as per AlliedSignal Aerospace Equipment Systems Service Bulletin

GT-242 Revision 2.

Note: FAA Airworthiness Directive 98-24-28 refers.

Compliance: At the next main fuel control visit to an AlliedSignal Aerospace Equipment Systems

authorised repair facility, regardless of the purpose of the visit, but no later than 31

October 1999.

This Airworthiness Directive becomes effective on 22 April 1999.

Background: This directive has been issued to require the replacement of beryllium copper fuel

control Pc bellows. The requirement follows reports of leaking bellows resulting in

uncommanded minimum fuel flow conditions, loss of fuel flow control and

subsequent forced landings.