

DHC-6 (Twin Otter) Series Aeroplanes

AD/DHC-6/16
Amdt 5

Wing Front Spar Attachment Fittings

3/87

Applicability: All models with serial numbers 1 to 210 inclusive.

Requirement: Action in accordance with de Havilland of Canada Service Bulletin No 6/174 Revision D, Part A or Part B as applicable.

Compliance: For Part A of SB 6/174: At intervals not exceeding 500 hours time in service or 3 months, whichever occurs first.

For Part B of SB 6/174: Within 100 hours time in service after 31 July 1974, unless already accomplished.

Note: The repetitive inspections of Part A may be discontinued upon installation of unused de Havilland fittings P/N C6WM 1133-1 and -2.

Background: Stress corrosion cracks have been found in service. The Service Bulletin requires inspection of the fittings and re- torquing of the wing attach bolts. This revision implements Revision D to the SB. Canadian AD's CF-69-4, CF-69-5 and CF-76-08 refer.