

DHC-6 (Twin Otter) Series Aeroplanes

---

**AD/DHC-6/65**

**Wing Strut Chafing**

**4/92**

Applicability: All models.

Requirement: Inspect for the presence of the protective nylon shield incorporated in the wing strut upper fairings by de Havilland Modification 6/1581.

If the shield is not installed, visually inspect the struts for damage in accordance with de Havilland Service Bulletin 6/342, and incorporate Modification 6/1581.

*Note: Transport Canada Airworthiness Directive CF-91-30 dated 8 August 1991 refers.*

Compliance: 1. Inspect within 25 hours time in service after 2 April 1992.  
2. Modify before 25 June 1992.

Background: Transport Canada's aging aircraft review identified this as mandatory action.