

AMD Falcon 50 and 900 Series Aeroplanes

---

**AD/AMD 50/7  
Amdt 1**

**Nose Gear Shock Absorber**

**11/94**

Applicability: Falcon 900 aircraft.

Requirement: Action in accordance with Dassault Aviation Alert Service Bulletin F900-150.

*Note: DGAC AD 94-098-014(B)R1 refers.*

Compliance: Unless already accomplished, prior to 13 November 1994.

Background: The manufacturer had defined a procedure to check the charge of the low pressure chamber of the nose gear shock absorber. This action was required to prevent the possibility of a gear retraction when the nose gear is not fully extended.

Amendment 1 is issued in response to a revision of the relevant DGAC AD which requires a modification that is designed to interrupt retraction of the landing gear when the NLG shock absorber is not fully extended.