

AMD Falcon 50 and 900 Series Aeroplanes

---

**AD/AMD 50/8**

**Cockpit Brake Pressure Lines**

**13/95  
DM**

Applicability: All Falcon 900 aircraft.

Requirement: Unless previously carried out action in accordance with Dassault Aviation Alert Service Bulletin F900-A29-4.

Compliance: Within 50 hours time in service from 17 October 1995.

Background: The manufacturer has advised that chaffing of the cockpit LH side brake pressure lines may occur.