

Boeing 727 Series Aeroplanes

**AD/B727/95
Amdt 2**

Outer Wing Upper Stringers

12/88

Applicability: All models.

Requirement: Action in accordance with Boeing Alert SB No. 727-57A159 Rev 3 including Notice of Status Change No 727-57A159 NSC1.

Note: FAA AD 88-17-06 Amdt 39-5988 refers.

Compliance: As per Requirement document.

Background: Extensive cracking has been found in wing upper stringers at various rib locations. Previous repairs may not have been effective. Revision 3 to the ASB introduced further inspection and some rework. This amendment references the latest FAA AD but does not change the requirement.