

Boeing 737 Series Aeroplanes

---

**AD/B737/75**

**Passenger Oxygen System**

**3/93**

**Applicability:** Model 737 series airplanes listed in Boeing Alert Service Bulletins 737-35A1037 dated 13 February 1992 and 737-35A1038 dated 19 March 1992.

**Requirement:**

1. For airplanes identified in Boeing Alert Service Bulletin 737-35A1037 dated 13 February 1992, modify the test stop plungers in the lavatory oxygen box assemblies in accordance with Boeing Alert Service Bulletin 737-35A1037 dated 13 February 1992.
2. For airplanes identified in Boeing Alert Service Bulletin 737-35A1038 dated 19 March 1992, modify the modular lavatory "A" oxygen box assemblies in accordance with Boeing Alert Service Bulletin 737-35A1038 dated 19 March 1992.

*Note: FAA AD 92-25-04 Amendment 39-8419 refers.*

**Compliance:** Within 900 flight hours or six calendar months from the issue date of this Directive, whichever occurs later.

**Background:** This Directive is issued to correct a condition that may prevent the availability of oxygen to passengers during a loss of cabin pressure.