

Boeing 747 Series Aeroplanes

---

**AD/B747/23                      Outboard Engine Strut Diagonal Brace Forward                      7/80**  
**Clevis Root - Inspection and Modification**

Applicability:    All model 747 equipped with CF6, JT9D-3 or JT9D-7 engines.

Document:        1. FAA AD 80-08-02, Amdt. 39-3738; or  
                         2. Boeing SB No. 747-54-2070.

Compliance:     As per requirement document No. 1.

Background:     An overseas operator has detected transverse cracks in clevis root of brace. Defect is attributed to local thickness being less than specified.