

Boeing 747 Series Aeroplanes

AD/B747/25 Wing Leading Edge Flap System - Modification 1/81

Applicability: All models 747.

Document: 1. FAA AD 80-19-05, Amdt. 39-3906; or
 2. Boeing SB No. 747-27-2204.

Compliance: As per requirement document No. 1.

Background: Investigation has revealed that a single electrical fault in the leading edge flap circuits could cause an unscheduled deployment of the flaps.