

Boeing 747 Series Aeroplanes

---

**AD/B747/29**

**Fairing Mounted Escape Slide Firing  
Mechanism - Rigging Revision**

**12/81**

Applicability: All model B747 aeroplanes with S/Nos. referenced in Boeing SB 747-25A2581 or with S/Nos. referenced in subsequent issues or revisions of that SB.

Document: Boeing SB 747-25A2581.

Compliance: Within 1200 hours time in service after 31 December 1981.

Background: Failure of escape slide to inflate due to reduced fairing door travel restricting the inflation firing mechanism.