

Boeing 747 Series Aeroplanes

AD/B747/56

Fuselage - Tail Section Structure

2/87

Applicability: All models with line numbers 001 to 554.

Requirement: Action in accordance with Boeing SB 747-53-2220 R2.

Note: FAA AD 86-16-05 refers.

Compliance: As per Requirement Document.

Background: The manufacturer reports instances of in-flight cabin pressure loss due to aft pressure bulkhead corrosion or deterioration of the composite Auxiliary Power Unit (APU) duct pressure pan.