

Boeing 747 Series Aeroplanes

AD/B747/59 Fuselage Upper Body Tear Strap Disbonding 11/87

Applicability: All models listed in the Requirement Document.

Requirement: Action in accordance with Boeing SB 747-53A2279 R1.

Note: FAA AD 87-16-13 refers.

Compliance: Inspect in accordance with the Requirement Document until terminating action carried out.

Background: Disbonding of the upper body hot bonded skin tear straps has been reported.