

Boeing 747 Series Aeroplanes

AD/B747/102

P180-1 Terminal Strip Nuts

**2/92
DM**

Applicability: As specified in the requirement document.

Requirement: Action in accordance with the technical requirements of FAA AD 91-23-09.

Compliance: Prior to 10 January 1992.

Background: The FAA have advised that a report has been received of loss of battery power due to a loose power feeder terminal connection. This condition, if not corrected, could result in fire and/or loss of electrical power to flight critical systems in the event of failure of the aircraft primary electrical power system.