

Boeing 767 Series Aeroplanes

AD/B767/34

Control Wheel Aids Transducer

4/90

Applicability: All models listed in the referenced Service Bulletin.

Requirement: Action in accordance with Boeing Alert SB 767-31A-0029.

Note: FAA AD 89-24-05 also refers.

Compliance: Prior to 30 April 1990.

Background: Removal of the AIDS transducer is required to prevent binding of the control wheel.