COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Boeing 767 Series Aeroplanes

AD/B767/40 Aft Equipment/Lavatory/Galley 9/90 Ventilation Fan Wire Bundles

Applicability: All Boeing 767 series aeroplanes as detailed in the Requirement document.

Requirement: Re-route the aft equipment/lavatory/galley ventilation fan wire bundles along the

frame assembly at Stn 1540 IAW Boeing ASB 767-21A0074.

Note: FAA AD 90-08-13 also refers.

Compliance: Prior to 6 September 1991.

Background: This AD is prompted by a report of charred insulation blankets aft of station 1540

which resulted from arcing and burning of damaged wire bundles. This condition, if

not corrected, could result in a fire behind the aft cargo compartment wall. Compliance with this AD is required in order to minimise the possibility of

inadvertent damage to the wire bundles.