

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AS 355/34 Amdt 1.

---

### **Eurocopter AS 355 (Twin Ecureuil) Series Helicopters**

**AD/AS 355/34  
Amdt 1**

**Rotating Swashplate Bearing**

**9/2009**

Requirement: CANCELLED.

This AD is cancelled on 27 August 2009.

Background: This Australian AD specified actions in accordance with SB No. 62-16. These actions included lubrication of the swashplate bearing every 100 hours, and a visual inspection by the pilot after the last flight of the day. French AD 89-156-039 (B) and USA AD 2004-05-23 refer. The current Airworthiness Limitations Section of the Eurocopter AS 355 maintenance manual contains requirements for inspecting and lubricating the main rotor swashplate at intervals not exceeding 100 hours time-in-service.



David Villiers  
Delegate of the Civil Aviation Safety Authority

30 June 2009