

Eurocopter AS 355 (Twin Ecureuil) Series Helicopters

AD/AS 355/38

Tail Rotor Drive Shaft Bearings

**11/91
DM**

- Applicability: All AS 355 helicopters versions E, F, F1, F2 and N equipped with P/N P.9107.NPP7 FAFNIR tail rotor drive shaft bearings not marked with an "X" on the seal flange.
- Requirement: Action in accordance with the Technical Requirements of DGAC AD 91-158-044 (B) for all aircraft acceptance tested by Aerospatiale Marignane between 15 May 1991 and 20 July 1991 or prior to 15 May 1991 and have operated less than 100 hours time in service.
- Note: Aerospatiale Telex Service No. 01-35 refers.*
- Compliance: By 30 August 1991 or prior to issue of Australian C of A, whichever occurs first.
- Background: Corroded bearings which could seize may have been fitted to the tail rotor drive shaft.