

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/B-2/27.

---

### Brantly B-2 Series Helicopters

**AD/B-2/27**

**Tail Rotor Blades Strike  
Indicators - Installation**

**6/2009**

Requirement: CANCELLED.

This AD is cancelled on 4 June 2009.

Background: This AD, issued in 1968, required installation of tail strike indicators in accordance with Brantly SL No.73 to provide positive indication of minor tail rotor strikes. The AD compliance was within 100 hours time in service after 21 March 1968. As all aircraft would have been modified, the AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

17 April 2009