

---

## AIRWORTHINESS DIRECTIVE

---

For the reasons set out in the background section, the CASA delegate whose signature appears below issues the following Airworthiness Directive (AD) under subregulation 39.1 (1) of CASR 1998. The AD requires that the action set out in the requirement section (being action that the delegate considers necessary to correct the unsafe condition) be taken in relation to the aircraft or aeronautical product mentioned in the applicability section: (a) in the circumstances mentioned in the requirement section; and (b) in accordance with the instructions set out in the requirement section; and (c) at the time mentioned in the compliance section.

---

### Turbomeca Turbine Engines - Arrius Series

**AD/ARRIUS/5**

**Turboshaft Engine Unairworthy**

**8/2003  
DM**

Applicability: Arrius 2F turboshaft engine serial number (S/N) 34084.

Requirement: Remove Arrius 2F engine (S/N) 34084 from service.

*Note: DGAC AD U2003-219(A) refers.*

Compliance: Before further flight.

This Airworthiness Directive becomes effective on 2 July 2003.

Background: This engine may have been damaged during its theft whilst in transport to the overhaul facility.



Jim Coyne  
Delegate of the Civil Aviation Safety Authority

26 June 2003