

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC-100/15.

---

### **S.L. Industries Commander 100 Series and Volair 10 Series Aeroplanes**

**AD/AC-100/15**

**Engine Mount Bolts - Inspection**

**9/2008**

Requirement: CANCELLED.

This AD is cancelled on 28 August 2008.

Background: This unique Australian AD, raised in 1973 against Aero Commander Service Bulletin (SB) No. 1012, required a modification to engine mounting bolts to ensure attainment of necessary torque.

Compliance was within 100 hours TIS after 30 April 1973.

As all affected aircraft would have been modified by now, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

17 July 2008