
AIRWORTHINESS DIRECTIVE

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/65.

Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/65

**Wing Spar Fillet Screws - Inspection
and Replacement**

8/2008

Requirement: CANCELLED.

This AD is cancelled on 31 July 2008.

Background: This unique Australian AD, raised in 1978 against Rockwell International (also known as Aero Commander) Service Bulletin (SB) No. 164, required an inspection and replacement of wing spar fillet screws with huck bolts. Compliance was required within 100 hours TIS after 1 March 1978, and thereafter at intervals not exceeding 100 hours TIS until replaced as per requirements document. As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers
Delegate of the Civil Aviation Safety Authority

20 June 2008