

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/71.

---

### **Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes**

**AD/AC/71                      Aft Engine Mount Attachment - Inspection                      8/2008**

Requirement:    CANCELLED.

This AD is cancelled on 31 July 2008.

Background:    This unique Australian AD, raised in 1980, against Rockwell International Service (also known as Aero Commander) Bulletin (SB) No. 173, required an inspection to ensure that the aft engine mount fittings of both engines are properly secured to the engine firewall. Compliance was required within 100 hours TIS after 31 October 1980. As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

20 June 2008