

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

**AD/AC/77**                      **Induction Air Elbow Duct - Replacement,  
Exhaust System - Inspection**                      **11/82**

Applicability:    Model 685 with S/Nos. 12000 to 12043 and 12045 to 12066.

Document:        Gulfstream American SB 192.

Compliance:     Within 100 hours time in service after 31 December 1982.

Background:     A combination of exhaust system leakage and displaced induction ducting may cause exhaust gases to enter the cockpit and cabin.