

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/AC/78.

---

### **Twin Commander (Gulfstream/Rockwell/Aerocommander 500, 600 and 700) Series Aeroplanes**

**AD/AC/78**

**Flight Control Chain  
Connector Link - Inspection**

**8/2008**

Requirement: CANCELLED.

This AD is cancelled on 31 July 2008.

Background: This unique Australian AD, raised in 1983 against Gulfstream American (also known as Aero Commander) Service Letter (SL) No. 353, required an inspection to verify installation of flight control chain connector links, plates and keepers. Compliance was required within 100 hours TIS after 1 February 1983. As all affected aircraft would have been inspected, and, if necessary, modified long ago, this AD is no longer required.



David Villiers  
Delegate of the Civil Aviation Safety Authority

20 June 2008