

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

**AD/AC/90**

**Wing Station 39 Wing Ribs**

**5/95**

- Applicability: Models 690, 690A, and 690B S/n 11001 to 11566 and Model 685 S/n 12001 to 12066.
- Requirement: Modify the wing ribs at WS 39 in accordance with Twin Commander Service Bulletin 211 Rev 1 Part II.
- Compliance: Within 50 hours time in service after 25 May 1995, or at the next inspection for Maintenance Release issue after 25 May 1995, whichever occurs first.
- Background: This Directive is issued to prevent an under-strength condition developing in the wing ribs at WS 39, and is part of the requirements of FAA AD 94-04-12.
- This Directive will be amended to include the spar cap and stringer inspections of FAA AD 94-04-12, if subsequent information is received indicating that this is necessary.