

Twin Commander (Gulfstream/Rockwell/ Aerocommander 500, 600 and 700) Series Aeroplanes

AD/AC/94

Airspeed in Turbulence

13/95 DM

Applicability: The following aircraft models and serial numbers:

Models	Serial Numbers
680T and 680V	1473 through 1720
680W	1721 through 1850
681	6001 through 6072
690	11001 through 11079
690A	11100 through 11344
690B	11350 through 11566
690C	11600 through 11735
690D	15001 through 15042
695	95000 through 95084
695A	96000 through 96100
695B	96201 through 96208

Requirement: Attach a placard on the windshield centre post in accordance with the Accomplishment Instructions of Twin Commander Service Bulletin 220.

A separate direction under CAR 138(3) for incorporation of the applicable flight manual amendment is being provided to Certificate of Registration holders.

Note: FAA AD 95-19-18 Amdt 39-9379 refers.

Compliance: Within 50 hours time in service after 25 October 1995.

Background: This Directive is issued in response to the recent issue of the above referenced AD by the FAA. Although no limitations have changed, the country of origin regulatory authority requires a placard and a flight manual amendment to warn the pilot to observe turbulent air penetration speeds.