

Aermacchi - Lockheed AL 60 Series Aeroplanes

---

**AD/AL 60/11**

**Engine Mounting Plates - Inspection  
and Modification**

**2/75**

Applicability: All models not incorporating Modification MB-L-001.

Requirement: 1. Inspect the engine mounting plates for cracks using a Dye Penetrant Technique in accordance with Aermacchi Lockheed Service Bulletin No. SB-L-0003.

2. Modify the engine mounting plates in accordance with Aermacchi Lockheed Modification Bulletin No. MB-L-0001.

Compliance: For para. 1 - Within 10 hours time in service after 20 January 1975 and thereafter at intervals not exceeding 100 hours time in service until modified.

For para. 2 - Before achieving 1200 hours total time in service.