

Airtractor AT-300, 400 and 500 Series Aeroplanes

AD/AT/5

**Engine Mount Ring on Vibro-Damp
Mount Assembly - Inspection**

7/83

Applicability: All models AT-300 and AT-301.

Document: Snow Engineering Co. Service Letter No. 50.

Compliance: 1. Within 100 hours time in service after 31st July 1983 and thereafter as per requirement document.
2. Repeat bolt removal at each 1000 hours time in service.

Background: The manufacturer reports cracking of attach brackets and excessive wear of attachment bolts.