

Cessna 150, F150, 152 & F152 Series Aeroplanes

---

**AD/CESSNA 150/34                      Flap Actuator Screw Mechanical Stop                      3/80**

Applicability:    Models 152 and A152 with S/Nos. 15279406 to 15284080, A1520735 to A1520919, F15201429 to F15201798 and FA1520337 to FA15200372.

Requirement:    Action in accordance with Cessna SIL No. SE 79-57.

*Note: FAA AD 80-01-06, Amendment 39-3649 refers.*

Compliance:    Within 100 hours time in service after 31 March 1980.

Background:     A mechanical stop is now available to prevent overtravel of the flap actuator assembly. Overtravel may lead to an asymmetric flap condition.