

Cessna 150, F150, 152 & F152 Series Aeroplanes

---

**AD/CESSNA 150/38**

**Aileron Hinge Pin**

**1/84**

Applicability: Model Serial Number

152	15282032 thru 15284659, 15284661 thru 15284684, 15284686 thru 15284851, 15284853 thru 15285417, 15285419 thru 15285621, 15285623 thru 15285625, 15285627 thru 15285651, 15285653 thru 15285681, 15285683, 15385685 thru 15285693, 15285695 thru 15285700, 15285702 thru 15285713, 15285716 thru 15285719, 15285722 thru 15285724, 15285726 thru 15285728, 15285730 thru 15285731, 15285733 thru 15285744, 15285748, 15285750, 15285751, 1528575 15285756, 15285757, 15285759, 15285760, 1528576 15285765, 15285767, 15285769, 15285772, 1528577, 15285778, 15285779, 15285781, 15285783
A152	A1520809 thru A1520990, A1520992 thru A1520997, A1520999 thru A1521020, A1521022
F152	F15201529 thru F15201883, F15201885 thru F15201896, F15201898 thru F15201931, F15201933 F15201935, F15201936
FA152	FA1520348 thru FA1520382.

Requirement: Action in accordance with Cessna S.I.L. SE 83-18.

*Note: FAA AD 83-22-06 refers.*

Compliance: Unless already accomplished within 100 hours time in service after 31 January 1984 or at the next scheduled inspection for Maintenance Release issue after 31 January 1984 whichever is the later.

Background: Possible migration and loss of the aileron hinge pin could result if the retaining split pin holes are incorrectly located.