

BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 90-193-032(B)R2

In case of any difficulty, reference should be made to the French original issue.

All types of ATR aircraft

Hydraulic system : Low pressure warning

The present Airworthiness Directive applies to all type of ATR aircraft :

- ATR 42-200, ATR 42-300, ATR 42-320
- ATR 72-101, ATR 72-102, ATR 72-201, ATR 72-202

on which modification 3082 has not been embodied.

In order to avoid any reversal of the hydraulic fluid low level detectors on the blue and green systems at the reservoir level - which could result in cutting off the pump of the system not affected - the following measurements are made mandatory except if those ones are already in force :

- Within 7 days after receipt of this Airworthiness Directive check to correct operation of the hydraulic fluid low level detectors on the blue and green systems and identify them by colour marking following the indications of Alert Service Bulletin AT 42-29-A0013 or of Alert Service Bulletin ATR 72-29-A1003.

Cf. : Service Bulletin ATR 42-29-A0013
Service Bulletin ATR 72-29-A1003

The present Revision 2 cancels and replaces AD 90-193-032(B)R1 dated June 17, 1992.

EFFECTIVE DATE : UPON RECEIPT

July 8, 1992

All types of ATR Aircraft

90-193-032(B)R2