

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive

Translation of 'Consigne de Navigabilité'

Réf.: 91-067-005(B)

In case of any difficulty, reference should be made to the French original issue.

ATR 72 aircraft series 100 ; 200

Flight controls

This Airworthiness Directive applies to ATR 72-101, -201, -102 and -202 aircrafts, serial numbers 126 to 189, 195, 198, 210.

The following steps are made mandatory in order to prevent failure of the rudder pedal connection rod :

- A. Before April 1, 1991, identify the make of the rudder pedal connection rod, following the instructions of S.B. ATR 72-27-1015.

If the rod is a TAC rod, no further action is required.

- B. If the inspection required in paragraph A shows that a SARMA rod has been installed, before June 15, 1991 replace it by a TAC rod or a SARMA rod identified P/N 14132 C by the constructor, following the instructions of S.B. ATR 72-27-1015.

Ref. B.S. ATR 72-27-1015

EFFECTIVE DATE : MARCH 30, 1991

March 20, 91

ATR 72 series 100 ; 200

91-067-005(B)