

BUREAU VERITAS

## AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'

Réf.: 91-215-006(B)

In case of any difficulty, reference should be made to the French original issue.

### ATR 72 aircraft

Flight controls

This Airworthiness Directive concerns ATR 72 101, 102, 201 and 202, serial numbers 108 to 186 inclusive and 195.

In order to ensure correct attachment of tabs on the elevator, the following actions are made mandatory :

- Within 300 flight hours following the effective date of this Airworthiness Directive, replace the elevator tab hinge lock nut pins, according to the instructions of SB ATR 72-55-1001, unless this has already been done.

Inform the ATR Product Support of the results of the inspection.

Ref. : SB ATR 72-55-1001

EFFECTIVE DATE : OCTOBER 12, 1991

October 2, 91

ATR 72 aircraft

91-215-006(B)