

GSAC

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 98-072-036(B)
In case of any difficulty, reference should be made to the French original issue.

ATR

ATR 72 aircraft

Flaps support beams

1/ INVOLVED MATERIAL :

This Airworthiness Directive applies to ATR 72 aircraft model -212A on which ATR modification 4831 has not been embodied.

2/ ACTIONS :

Modify the flaps support beams in accordance with Service Bulletin ATR 72-57-1020 instructions in order to restore their fatigue life.

3/ COMPLIANCE TIME :

Before accumulation of 24,000 flights.

4/ REFERENCES :

- Service Bulletin ATR 72-57-1020 original issue or any further approved revisions.

EFFECTIVE DATE : FEBRUARY 21, 1998

n/GH

February 11, 1998

ATR
ATR 72 aircraft

98-072-036(B)