

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PHZL/23 Amdt 5.

---

### Propellers - Variable Pitch - Hartzell

**AD/PHZL/23**                      **Blade Shank - Inspection and Modification**                      **13/2005**  
**Amdt 5**

Requirement:      CANCELLED.

This AD is cancelled on 22 December 2005.

Background:      This AD was raised requiring certain inspections and work on Hartzell double shoulder blades. This Directive reflected the requirements of FAA AD 68-13-02 and 68-19-04 which both referenced Hartzell Service Bulletin (SB) 93. That SB has been superseded by SB 217 which is mandated by FAA AD 97-18-02R1. Hartzell SB 217 covers a wider range of propellers identified in earlier AD's. FAA AD 97-18-02R1 superseded FAA AD's 68-13-02 and 68-19-04, 77-14-07 and 77-17-34. As a result AD/PHZL/69 Amdt 2 was issued which expands on the requirements of this AD.



James Coyne  
Delegate of the Civil Aviation Safety Authority

11 November 2005