

---

## AIRWORTHINESS DIRECTIVE

---

On the effective date specified below, and for the reasons set out in the background section, the CASA delegate whose signature appears below revokes Airworthiness Directive AD/PHZL/50.

---

### Propellers - Variable Pitch - Hartzell

**AD/PHZL/50**

**A-4025 Spring Retainer - Inspection**

**4/2009**

Requirement: CANCELLED.

This AD is cancelled on 9 April 2009.

Background: This unique Australian AD was raised in 1984 against Hartzell Service Letter (SL) No. 149 requiring a one time inspection for cracks on A-4025 feathering cup spring retainer as used in Hartzell five blade turbine propeller model HC-B5MP-3( )/ M10282AB+6, M10876(B,K).

Compliance was at next reconditioning or rectification necessitating disassembly, whichever is the sooner.

Given the extended period this AD has been promulgated, and that affected spring retainers would have been inspected by now, this AD is considered to be no longer required.



James Coyne  
Delegate of the Civil Aviation Safety Authority

19 February 2009