

Seats and Berths

---

**AD/SEATS/11**                      **First Class Seats Motor System Cable**                      **11/97**

Applicability:    Britax Rumbold first class seats fitted on Boeing 747, Boeing 777, and McDonnell Douglas DC-10 aircraft.

Requirement:    Inspect in accordance with Britax Rumbold Service Bulletin SBM13000-25-929.

*Note: UK CAA AD 003-05-97 refers.*

Compliance:    Before 9 January 1998 for the initial inspection, and thereafter at intervals not to exceed 6 months; until Britax Rumbold Service bulletin SBM13000-25-911 (Modification CRR SE012) is incorporated.

This Airworthiness Directive becomes effective on 9 October 1997.

Background:    The CAA requires certain actions because damage and wear to the cable could be caused by movement of the seat sliding trolley.