COMMONWEALTH OF AUSTRALIA CIVIL AVIATION SAFETY AUTHORITY SCHEDULE OF AIRWORTHINESS DIRECTIVES

Supplementary Equipment

AD/SUPP/11

Bronzavia-Air Equipment Rescue Hoist Attach Brackets

12/88

Applicability: Electric Rescue Hoists P/N 76370 76370-010 76370-011 76370-020 76370-030.

Requirement: Action in accordance with Bronzavia - Air Equipment SB 25-62-OJ.

Note 1: DGAC AD 88-087(B) refers.

Note 2: Installation of CRS bracket P/N 709883-100 and 709884-100 terminates the

 $in spection\ requirements.$

Note 3: For the purposes of the repetitive inspection requirement, prior inspections to AD/ECUREUIL/38 Amdt 1 and AD/AS 355/27 are acceptable as compliance with

this Directive.

Compliance: Within 10 hours time in service after 1 December 1988 and thereafter every 200

hours time in service.

Background: The manufacturer has reported that angle brackets were seriously cracked. Since that

time a terminating modification has been developed.