

**State of Israel
Ministry of Transport
Civil Aviation Authority**

**AD ISR I-57-2021-12-3R1
Rev. Date: 01 Jan. 2024
Issue Date: 01 Jan. 2022**

AIRWORTHINESS DIRECTIVE

This Airworthiness Directive, issued by the Civil Aviation Authority in accordance with the Israeli Air Navigation Regulations applies to an aircraft for which our records list you as the registered owner. It affects aviation safety and requires your immediate attention. No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with that Directive.

- APPLIES TO:** GALP model G150 aircraft serial numbers 201 through 326 certificated in any category.
- SUBJECT:** **Wings-Flaps-Fairing Seal Repair**
- REASON:** Prevent possibility of flap fairing debonding, moisture intrusion and wing lower skin corrosion at rib 3 and rib 11.
- REASON FOR REV.1** Update compliance time of initial issue of AD ISR-I-57-2021-12-3
- ACTION:** Remove L/H and R/H wing flap fairings, inspect and reseal fillet seal between left and right wings structure and fairing in accordance with Gulfstream Service Bulletin No. 150-57-197 dated January 01, 2022 or later approved revision.
- COMPLIANCE:** Unless already accomplished, comply with this AD at the next suitable planned maintenance inspection within the next 24 months from the effective date of this AD
- EFFECTIVE DATE:** Rev. 1: February 15, 2024.
Initial issue: February 15, 2022.

FOR FURTHER INFORMATION CONTACT: Mr.Saul Pascal, Engineering Branch, CAAI - P.O.Box 1101, 3 Golan Street, Airport City, Israel, 70151 Telephone: 972-3-9774583, Fax: 972-3-9774592, E-mail: pascals@mot.gov.il